

Lycery North Village Hall - Risk assessment

Assessor(s): Ian Kidd

Date: 19 Jul 2018

Review Date: 10 Dec 2019

Likelihood of Occurrence (L)		Risk Rating	
1 - Not Likely	1 - Insignificant	1 - 5 Acceptable (Low)	Rating (R)
2 - Possible	2 - Slight	6 - 11 Tolerable (Medium)	
3 - Quite Possible	3 - Moderate	12 - 25 Unacceptable (High)	
4 - Likely	4 - High		
5 - Very Likely	5 - Very High		

HAZARD	THOSE AT RISK	IS THE RISK ADEQUATELY CONTROLLED?	Risk Rating L x S = R	Risk	WHAT FURTHER ACTION IS REQUIRED TO CONTROL RISK?
List hazards here.	List groups of people at risk from hazards identified.	List existing controls here or note where information can be found.	(if rating is 12 or more, additional controls to be implemented)	Low Medium High	List the risks which are not adequately controlled and the actions proposed where it is reasonably practicable to do more.
Slips, trips and falls Eg uneven surface of car park, cleaning floors etc.	Users of the hall and car park may suffer injuries such as fractures or bruising if they slip, eg on spillages or trip over objects.	Car Park surface tarmacked in 2014 and maintained to be as even as possible. Parking spaces for visitors with disabilities available near to hall entrance. Good lighting in car park and all rooms, movement operated in entrance lobby, toilets and corridors in hall. Users know (through hire agreement) to clear up spillages immediately and know where equipment for this is kept. Mats at entrances to stop rain water being carried in. No trailing electrical leads / cables	2 3 6	Medium	